

## WATCHDOG PRODUCT LINE

### STANDARD FEATURES

### OPTIONAL SENSORS & ACCESSORIES

**REFERENCE:**

- STANDARD
- OPT OPTIONAL
- BLANK NOT AVAILABLE

Parameters:  
Item

	Evapotranspiration	LCD Display	Wireless-Ready	Alarm Output-Ready	Air Temperature Sensor	Relative Humidity Sensor	Dew Point	Wind Speed and Direction	Tipping Bucket Rain Collector	Solar Radiation Sensor	External Sensor Ports	Quantum Light Sensor	Ext.(Soil) Temperature Sensor	Leaf Wetness Sensor	Watermark Soil Moisture	Barometric Pressure Sensor
	ET	LCD	3391	Alrm	Tmp	RH	Dew	Wind	Rain	Solar		PAR	Temp	LW	SM	Bar
				3672					3665R	3670I		3668I	3667	3666	6450WD	3671

**Weather Stations** (prepackaged units with LCD display, external sensor ports, and wireless communication options)

2900ET	3350WD2	•	•	•	•	•	•	•	•	•	5	OPT	OPT	OPT	OPT	OPT
2800	3345WD2		•	•	•				OPT	OPT	9	OPT	OPT	OPT	OPT	OPT
2700	3340WD2		•	•	•	•	•	•	•	OPT	6	OPT	OPT	OPT	OPT	OPT
2600	3325WD2		•	•	•	•		•	•	OPT	6	OPT	OPT	OPT	OPT	OPT
2550	3320WD2		•	•	•	•	•	•		OPT	6	OPT	OPT	OPT	OPT	OPT
2525	3315WD2		•	•	•	•		•		OPT	6	OPT	OPT	OPT	OPT	OPT

**2000 Mini Station** (affordable 4 channel datalogging units, featuring LCD display and wireless communication options)

2475	3686WD		•	•	•	•	•		OPT	OPT	1	•	OPT	OPT	OPT	OPT
2450	3684WD		•	•	•	•	•		OPT	OPT	2	OPT	OPT	OPT	OPT	OPT
2425	3683WD		•	•	•	•			OPT	OPT	3	OPT	OPT	OPT	OPT	OPT
2400	3685WD		•	•	•				OPT	OPT	4	OPT	OPT	OPT	OPT	OPT

**200-400 Series Mini-Stations** (mix and match components for affordable 2-4 channel datalogging units featuring LCD display)

450	3684		•		•	•			OPT	OPT	2	OPT	OPT	OPT	OPT	
425	3683		•		•				OPT	OPT	3	OPT	OPT	OPT	OPT	
400	3685		•						OPT	OPT	4	OPT	OPT	OPT	OPT	
250	3682		•		•	•					0					
225	3681		•		•				OPT	OPT	1	OPT	OPT	OPT	OPT	
200	3680		•						OPT	OPT	2	OPT	OPT	OPT	OPT	

**100 Series Economy Loggers** (economic datalogging units for 1-2 parameters)

LW/Temp	3610TWD				•						0			•		
Rain	3554WD								•		0					
150	3612WD				•	•					0					
125	3617WD				•						0		•			
115	3635WD								OPT		0					
110	3618WD				•						0					
100-2K	3619WD				•						0					(requires item 3655K2 Docking Station)
100-8K	3620WD				•						0					(requires item 3655K2 Docking Station)
100-T/RH	3621WD				•	•					0					(requires item 3655K2 Docking Station)

**Wireless Crop Monitor** (a base station with 1-16 wireless remote sensor units, ideal for greenhouse or frost monitoring)

T/RH	3540		•	•	•	•					0					
Temp	3545		•	•	•						1	OPT	OPT	OPT		

**Mobile Sprayer Station** (a compact unit providing on-the-go weather monitoring)

	3349SS				•	•	•	•			0					•
--	--------	--	--	--	---	---	---	---	--	--	---	--	--	--	--	---